

165269414

PATENT

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re application of David A. Sharp)
Serial No.: 10/766,417)
Filed: January 27, 2004)
For: BELT ALIGNMENT SYSTEM)
Art Unit: 3651)
Examiner: Unassigned)

I hereby certify that this paper is being deposited with
the United States Postal Service as FIRST-CLASS mail
in an envelope addressed to: Mail Stop Missing Parts,
Commissioner for Patents; P.O. Box 1450, Alexandria,
VA 22313-1450, on this date.

August 16, 2004

Date

Attorney for Applicants
Registration No. 31,497

Mail Stop MISSING PARTS
Commissioner for Patents
P.O. Box 1450
Alexandria, VA 22313-1450

CLAIM FOR PRIORITY

Sir:

Applicant claims foreign priority benefits under 35 U.S.C. § 119 on the basis of the
foreign application identified below:

Canadian Patent Application No. 2,419,286, filed February 10, 2003.

A certified copy of the priority document is enclosed.

August 16, 2004

Suite 2500
300 South Wacker Drive
Chicago, Illinois 60606
Tel. (312) 987-4002
Fax. (312) 360-9315

P:\DOCS\165269414\642080.DOC

GREER, BURNS & CRAIN, LTD.

By

Lawrence J. Crain

Registration No. 31,497



Office de la propriété
intellectuelle
du Canada

Un organisme
d'Industrie Canada

Canadian
Intellectual Property
Office

An Agency of
Industry Canada

*Bureau canadien
des brevets
Certification*


La présente atteste que les documents
ci-joints, dont la liste figure ci-dessous,
sont des copies authentiques des docu-
ments déposés au Bureau des brevets.

*Canadian Patent
Office
Certification*

This is to certify that the documents
attached hereto and identified below are
true copies of the documents on file in
the Patent Office.

Specification and Drawings, as originally filed, with Application for Patent Serial No:
2,419,286, on February 10, 2003, by DAVID A. SHARP, for "Sure Align Tracker".

**CERTIFIED COPY OF
PRIORITY DOCUMENT**


Agent certificateur/Certifying Officer

January 27, 2004
Date

BEST AVAILABLE COPY

Canada

(CIPO 68)

OPIC



CIPO

SECIFICATIONS

1. This invention relates to aligning conveyor belt systems on both carrying side and return side off conveyor belt.
2. It is common in a tracking devise for conveyor belts to fail prematurely. Carry back material {material that has not been removed by belt scraper at conveyor discharge} may cause material build up under other types of tracking rollers. Under the return side tracking roller is the roller support and pivot mechanism. This carries back material build up, causes rollers and pivot mechanism to seize. Other tracking devises don't aligned conveyor belt until belt is way off line. It is of coarse necessary to provide a proper pivoting and simple aligning method eliminate roller damage and ensure effective and simple operation. The installation and alignment principles must be simple and effective.
3. I have found that these disadvantages may be overcome by providing a devise, which controls misalignment continuously with minimum force. The pivoting mechanism and roller support is clear of any carry back material from damaging equipment.

BEST AVAILABLE COPY

CLAIMS

The self aligning tracking assembly comprises of figure #1A troughing support bracket, figure #1B return side return bracket, figure #2 pivot assembly, figure #3 tracking control bar, figure #4 adjustable guide rollers, figure #5 tracking roller.

In figure #1A the troughing support bracket is installed to the topside of the conveyor stringer. Remove troughing assembly and install support bracket.

In figure #1B the return side support brackets are installed to the under side of the conveyor stringers. Remove return roller and bolt support brackets to stringers. Be sure, brackets are mounted according to belt direction. (Refer to print if necessary).

The pivot assembly figure #2 is mounted on the support bracket and locked in place using lock nut.

The tracking control bar figure #3 is bolted to the pivot assembly torque arm, ensure to use washer between moving parts, to allow adequate movement.


In order to install tracking roller figure #5 it is necessary to raise the belt. Install tracking roller in slot provided on the pivot assembly.

Start conveyor belt, and adjust tracking control bar manually until belt is centrally aligned. Stop conveyor and ensure tracking roller is perpendicular to the belt. Install adjustable guide roller figure #4 in the slot provided in the tracking control bar. Adjust guide roller on both sides to within 1/4" of the belt. As the belt travels off centerline, the guide roller is activated, causing the pivot assembly to cause the tracking roller to pivot about the pivot axis to steer the belt back to its central position.

BEST AVAILABLE COPY

**selfaligning troughing
application**


figure#1a



BEST AVAILABLE COPY


FIG 1B

MOUNTING DIMENSIONS
* DIMENSIONS TO FOLLOW
CEMA STANDARD




SECTION A-A

FIG # 2



SECTION B-B

FIGURE#3



TOP VIEW

FIG. # 4

ADJUSTABLE ROLLER HEIGHT



GUIDE ROLLER

BELT TRAVEL

SECTION D-D

RIGHT SIDE VIEW RETURN SIDE

SCALE 1:5



FIG#4

GUIDE
ROLLER

HSS 1 1/2" x 1 1/2"

PIVOT

BELT ROLLER

25x 1/2" FLATB,

TORQUE ARM

BELT
TRAVEL

EDGE OF BELT

173

100

229

R98


12


144

185

SECTION


C-C





figure#5

scale 1:15



**This Page is Inserted by IFW Indexing and Scanning
Operations and is not part of the Official Record**

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:

- ☐ **BLACK BORDERS**
- ☐ **IMAGE CUT OFF AT TOP, BOTTOM OR SIDES**
- ☐ **FADED TEXT OR DRAWING**
- ☐ **BLURRED OR ILLEGIBLE TEXT OR DRAWING**
- ☐ **SKEWED/SLANTED IMAGES**
- ☐ **COLOR OR BLACK AND WHITE PHOTOGRAPHS**
- ☐ **GRAY SCALE DOCUMENTS**
- ☐ **LINES OR MARKS ON ORIGINAL DOCUMENT**
- ☐ **REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY**
- ☐ **OTHER:** _____

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.